

Outfalls inspected FY 2020

Outfall ID	District	Route	MilePost	Receiving water	Impaired	OAW
898997	Northcentral	I-15	9.13	Virgin River	✓	
985778	Southcentral	I-10	289.18	Cienega Creek		✓
986825	Southcentral	I-10	288.82	Cienega Creek		✓
1006202	Southcentral	I-10	284.96	Davidson Canyon		✓
1006204	Southcentral	I-10	284.28	Davidson Canyon		✓
1006274	Southcentral	I-10	284.41	Davidson Canyon		✓
1006380	Southcentral	I-10	284.17	Davidson Canyon		✓
1006409	Southcentral	I-10	284.29	Davidson Canyon		✓
1017172	Southcentral	SR 77	71.81	Rillito Creek		
1017220	Southeast	US 191	153.58	Gila River	✓	
1058178	Northcentral	I-17	339.85	Sinclair Wash		
1062492	Northcentral	SR 89A	382.28	Oak Creek	✓	✓
1069543	Northcentral	I-15	9.3	Virgin River	✓	
1069544	Northcentral	I-15	9.31	Virgin River	✓	
1069545	Northcentral	I-15	9.35	Virgin River	✓	
1069546	Northcentral	I-15	9.36	Virgin River	✓	
1069547	Northcentral	I-15	9.37	Virgin River	✓	
1069548	Northcentral	I-15	9.43	Virgin River	✓	
1069550	Northcentral	I-15	9.46	Virgin River	✓	
1485571	Northwest	SR 89	306.41	Granite Creek	✓	
1486080	Northwest	SR 89	306.33	Granite Creek	✓	
1486083	Northwest	SR 89	306.48	Granite Creek	✓	
1488480	Northwest	SR 69	287.98	Lynx Creek	✓	
1510550	Southcentral	SR 77	79.84	Canada del Oro		
1510619	Southeast	US 191	153.43	Gila River	✓	
1512473	Central	SR 202L	5.9	Salt River		
1512474	Central	SR 202L	7.99	Salt River		
1512475	Central	SR 202L	8.3	Salt River		
1512476	Central	SR 202L	8.45	Salt River		
1512477	Central	SR 202L	14.45	Salt River		
1512486	Central	SR 101L	51.38	Salt River		
1512487	Central	SR 101L	51.58	Salt River		
1512537	Central	SR 51	6.99	Salt River		
1512540	Central	SR 51	11.04	Salt River		
1512541	Central	SR 51	11.63	Salt River		
1512542	Central	SR 51	11.63	Salt River		
1512544	Central	I-17	208.84	Cave Creek		
1512546	Central	SR 101L	25.96	Cave Creek		
1512547	Central	SR 101L	21.87	Scatter Wash		
1512548	Central	SR 101L	21.82	Scatter Wash		
1512549	Central	SR 101L	21.24	Skunk Creek	✓	
1512550	Central	SR 101L	21.24	Skunk Creek	✓	
1512552	Central	SR 101L	16.73	New River		
1512556	Central	SR 101L	14.52	New River		
1512558	Central	US 60	159.57	Salt River		
1516715	Southcentral	SR 77	78.85	Canada del Oro		

Outfalls inspected FY 2020

Outfall ID	District	Route	MilePost	Receiving water	Impaired	OAW
1518523	Southcentral	SR 77	80.86	Canada del Oro		
1518809/1560894	Southcentral	SR 80	297.71	San Pedro River	✓	
1518814	Southeast	SR 80	343.26	Mule Gulch	✓	
1518815	Southeast	SR 80	343.26	Mule Gulch	✓	
1520653	Southcentral	SR 77	71.81	Rillito Creek		
1522248	Southcentral	I-10	284.65	Davidson Canyon		✓
2000246	Central	SR 202L	7.45	Salt River		
2029182	Southcentral	I-10	289.14	Cienega Creek		✓
2029183	Southcentral	I-10	289.14	Cienega Creek		✓
2029184	Southcentral	I-10	289.11	Cienega Creek		✓
2029186	Southcentral	I-10	289.1	Cienega Creek		✓
2029187	Southcentral	I-10	289.1	Cienega Creek		✓
2029195	Southcentral	I-10	289.24	Cienega Creek		✓
2029486	Southcentral	I-10	288.84	Cienega Creek		✓



A. OUTFALL IDENTIFICATION

- 1) Outfall ID:
- 2) Date of Inspection:
- 3) Time of Inspection:
- 4) Rainfall event within the last 72 hour: ☒ yes ☐ no
- 5) Inspector Name:

B. GENERAL OUTFALL DESCRIPTION

- 1) Route:
- 2) Milepost:
- 3) Type of Outfall (ex. large cmp, step down box culvert):

Structure with deck drains

C. FIELD OBSERVATIONS

Flow	Smell	Floatables	Vegetation/ Algae	Deposits
☒ Dry	☒ None	☒ None	☒ None	☒ None
☐ Standing	☐ Musty	☐ Sewage	☐ Minimal	☐ Debris
☐ Slow	☐ Sewage	☐ Oil Sheen	☐ Normal	☐ Sediment
☐ Moderate	☐ Rotten Eggs	☐ Soap Suds	☐ Excessive	☐ Water Line
☐ Fast	☐ Solvent	☐ Other:		☐ Other:
	☐ Chlorine			
	☐ Other:			

NOTE* If any of the above boxes are checked other than Dry or None, a photo must be taken and submitted as Attachment A.

D. ADDITIONAL NOTES

Virgin River Bridge #1, Str. # 1089

Northcentral District, Fredonia maintenance unit

Light drizzle occurring at time of inspection, no runoff observed



A. OUTFALL IDENTIFICATION

- 1) Outfall ID:
- 2) Date of Inspection:
- 3) Time of Inspection:
- 4) Rainfall event within the last 72 hour: ☐ yes ☒ no
- 5) Inspector Name:

B. GENERAL OUTFALL DESCRIPTION

- 1) Route:
- 2) Milepost:
- 3) Type of Outfall (ex. large cmp, step down box culvert):

Structure with deck drains

C. FIELD OBSERVATIONS

Flow	Smell	Floatables	Vegetation/ Algae	Deposits
☒ Dry	☒ None	☒ None	☒ None	☒ None
☐ Standing	☐ Musty	☐ Sewage	☐ Minimal	☐ Debris
☐ Slow	☐ Sewage	☐ Oil Sheen	☐ Normal	☐ Sediment
☐ Moderate	☐ Rotten Eggs	☐ Soap Suds	☐ Excessive	☐ Water Line
☐ Fast	☐ Solvent	☐ Other:		☐ Other:
	☐ Chlorine			
	☐ Other:			

NOTE* If any of the above boxes are checked other than Dry or None, a photo must be taken and submitted as Attachment A.

D. ADDITIONAL NOTES

Southcentral District, Tucson West maintenance unit

Cienega Creek Br EB, Str. #448



A. OUTFALL IDENTIFICATION

- 1) Outfall ID:
- 2) Date of Inspection:
- 3) Time of Inspection:
- 4) Rainfall event within the last 72 hour: ☐ yes ☒ no
- 5) Inspector Name:

B. GENERAL OUTFALL DESCRIPTION

- 1) Route:
- 2) Milepost:
- 3) Type of Outfall (ex. large cmp, step down box culvert):

C. FIELD OBSERVATIONS

Flow

- ☒ Dry
☐ Standing
☐ Slow
☐ Moderate
☐ Fast

Smell

- ☒ None
☐ Musty
☐ Sewage
☐ Rotten Eggs
☐ Solvent
☐ Chlorine
☐ Other:

Floatables

- ☒ None
☐ Sewage
☐ Oil Sheen
☐ Soap Suds
☐ Other:

Vegetation/
Algae

- ☐ None
☐ Minimal
☒ Normal
☐ Excessive

Deposits

- ☒ None
☐ Debris
☐ Sediment
☐ Water Line
☐ Other:

NOTE* If any of the above boxes are checked other than Dry or None, a photo must be taken and submitted as Attachment A.

D. ADDITIONAL NOTES

ATTACHMENT A
Photo Documentation of Flows



Outfall ID: 986825

Permit Year 2020



A. OUTFALL IDENTIFICATION

- 1) Outfall ID: 1006202
- 2) Date of Inspection: 3/30/2020
- 3) Time of Inspection: 1227
- 4) Rainfall event within the last 72 hour: ☐ yes ☒ no
- 5) Inspector Name: Laura Nordan and Michael Carlson

B. GENERAL OUTFALL DESCRIPTION

- 1) Route: I-10 WB
- 2) Milepost: 284.96
- 3) Type of Outfall (ex. large cmp, step down box culvert):

Unpaved cut ditch

C. FIELD OBSERVATIONS

Flow

- ☐ Dry
☒ Standing
☐ Slow
☐ Moderate
☐ Fast

Smell

- ☒ None
☐ Musty
☐ Sewage
☐ Rotten Eggs
☐ Solvent
☐ Chlorine
☐ Other:

Floatables

- ☒ None
☐ Sewage
☐ Oil Sheen
☐ Soap Suds
☐ Other:

Vegetation/
Algae

- ☐ None
☒ Minimal
☐ Normal
☐ Excessive

Deposits

- ☒ None
☐ Debris
☐ Sediment
☐ Water Line
☐ Other:

NOTE* If any of the above boxes are checked other than Dry or None, a photo must be taken and submitted as Attachment A.

D. ADDITIONAL NOTES

Southcentral District, Tucson West maintenance unit

Cut ditch drainage blocked by debris preventing flow

ATTACHMENT A
Photo Documentation of Flows



Outfall ID:

1006202

Permit Year 2020



A. OUTFALL IDENTIFICATION

- 1) Outfall ID: 1006204
- 2) Date of Inspection: 3/30/2020
- 3) Time of Inspection: 1236
- 4) Rainfall event within the last 72 hour: ☐ yes ☒ no
- 5) Inspector Name: Laura Nordan and Michael Carlson

B. GENERAL OUTFALL DESCRIPTION

- 1) Route: I-10 WB
- 2) Milepost: 284.28
- 3) Type of Outfall (ex. large cmp, step down box culvert):

Unpaved cut ditch

C. FIELD OBSERVATIONS

Flow	Smell	Floatables	Vegetation/ Algae	Deposits
☒ Dry	☒ None	☒ None	☒ None	☒ None
☐ Standing	☐ Musty	☐ Sewage	☐ Minimal	☐ Debris
☐ Slow	☐ Sewage	☐ Oil Sheen	☒ Normal	☐ Sediment
☐ Moderate	☐ Rotten Eggs	☐ Soap Suds	☐ Excessive	☐ Water Line
☐ Fast	☐ Solvent	☐ Other:		☐ Other:
	☐ Chlorine			
	☐ Other:			

NOTE* If any of the above boxes are checked other than Dry or None, a photo must be taken and submitted as Attachment A.

D. ADDITIONAL NOTES

Southcentral District, Tucson West maintenance unit

ATTACHMENT A
Photo Documentation of Flows



Outfall ID: 1006204

Permit Year 2020



Environmental Planning

Dry Weather Field Screening

Site Report Form

A. OUTFALL IDENTIFICATION

- 1) Outfall ID:
- 2) Date of Inspection:
- 3) Time of Inspection:
- 4) Rainfall event within the last 72 hour: ☐ yes ☒ no
- 5) Inspector Name:

B. GENERAL OUTFALL DESCRIPTION

- 1) Route:
- 2) Milepost:
- 3) Type of Outfall (ex. large cmp, step down box culvert):

Structure with deck drains

C. FIELD OBSERVATIONS

Flow	Smell	Floatables	Vegetation/ Algae	Deposits
☒ Dry	☒ None	☒ None	☒ None	☒ None
☐ Standing	☐ Musty	☐ Sewage	☐ Minimal	☐ Debris
☐ Slow	☐ Sewage	☐ Oil Sheen	☐ Normal	☐ Sediment
☐ Moderate	☐ Rotten Eggs	☐ Soap Suds	☐ Excessive	☐ Water Line
☐ Fast	☐ Solvent	☐ Other:		☐ Other:
	☐ Chlorine			
	☐ Other:			

NOTE* If any of the above boxes are checked other than Dry or None, a photo must be taken and submitted as Attachment A.

D. ADDITIONAL NOTES

Southcentral District, Tucson West maintenance unit

Davidson Canyon Bridge, Str. #784



Environmental Planning

Dry Weather Field Screening

Site Report Form

A. OUTFALL IDENTIFICATION

- 1) Outfall ID:
- 2) Date of Inspection:
- 3) Time of Inspection:
- 4) Rainfall event within the last 72 hour: ☐ yes ☒ no
- 5) Inspector Name:

B. GENERAL OUTFALL DESCRIPTION

- 1) Route:
- 2) Milepost:
- 3) Type of Outfall (ex. large cmp, step down box culvert):

Cut ditch

C. FIELD OBSERVATIONS

Flow

- ☒ Dry
☐ Standing
☐ Slow
☐ Moderate
☐ Fast

Smell

- ☒ None
☐ Musty
☐ Sewage
☐ Rotten Eggs
☐ Solvent
☐ Chlorine
☐ Other:

Floatables

- ☒ None
☐ Sewage
☐ Oil Sheen
☐ Soap Suds
☐ Other:

Vegetation/ Algae

- ☐ None
☐ Minimal
☒ Normal
☐ Excessive

Deposits

- ☒ None
☐ Debris
☐ Sediment
☐ Water Line
☐ Other:

NOTE* If any of the above boxes are checked other than Dry or None, a photo must be taken and submitted as Attachment A.

D. ADDITIONAL NOTES

Southcentral District, Tucson West maintenance unit

ATTACHMENT A
Photo Documentation of Flows



Outfall ID: 1006380

Permit Year 2020



A. OUTFALL IDENTIFICATION

- 1) Outfall ID: 1006409
- 2) Date of Inspection: 3/30/2020
- 3) Time of Inspection: 1240
- 4) Rainfall event within the last 72 hour: ☐ yes ☒ no
- 5) Inspector Name: Laura Nordan and Michael Carlson

B. GENERAL OUTFALL DESCRIPTION

- 1) Route: I-10 WB
- 2) Milepost: 284.29
- 3) Type of Outfall (ex. large cmp, step down box culvert):

Unpaved cut ditch

C. FIELD OBSERVATIONS

Flow	Smell	Floatables	Vegetation/ Algae	Deposits
☒ Dry	☒ None	☒ None	☐ None	☐ None
☐ Standing	☐ Musty	☐ Sewage	☐ Minimal	☒ Debris
☐ Slow	☐ Sewage	☐ Oil Sheen	☒ Normal	☐ Sediment
☐ Moderate	☐ Rotten Eggs	☐ Soap Suds	☐ Excessive	☐ Water Line
☐ Fast	☐ Solvent	☐ Other:		☐ Other:
	☐ Chlorine			
	☐ Other:			

NOTE* If any of the above boxes are checked other than Dry or None, a photo must be taken and submitted as Attachment A.

D. ADDITIONAL NOTES

Southcentral District, Tucson West maintenance unit

ATTACHMENT A
Photo Documentation of Flows



Outfall ID:

1006409

Permit Year 2020



Environmental Planning

Dry Weather Field Screening

Site Report Form

A. OUTFALL IDENTIFICATION

- 1) Outfall ID:
- 2) Date of Inspection:
- 3) Time of Inspection:
- 4) Rainfall event within the last 72 hour: ☐ yes ☒ no
- 5) Inspector Name:

B. GENERAL OUTFALL DESCRIPTION

- 1) Route:
- 2) Milepost:
- 3) Type of Outfall (ex. large cmp, step down box culvert):

Structure with deck drains

C. FIELD OBSERVATIONS

Flow	Smell	Floatables	Vegetation/ Algae	Deposits
☒ Dry	☒ None	☒ None	☒ None	☒ None
☐ Standing	☐ Musty	☐ Sewage	☐ Minimal	☐ Debris
☐ Slow	☐ Sewage	☐ Oil Sheen	☐ Normal	☐ Sediment
☐ Moderate	☐ Rotten Eggs	☐ Soap Suds	☐ Excessive	☐ Water Line
☐ Fast	☐ Solvent	☐ Other:		☐ Other:
	☐ Chlorine			
	☐ Other:			

NOTE* If any of the above boxes are checked other than Dry or None, a photo must be taken and submitted as Attachment A.

D. ADDITIONAL NOTES

Southcentral District, Tucson East maintenance unit

Rillito Creek Bridge Str. #1550



Environmental Planning

Dry Weather Field Screening

Site Report Form

A. OUTFALL IDENTIFICATION

- 1) Outfall ID:
- 2) Date of Inspection:
- 3) Time of Inspection:
- 4) Rainfall event within the last 72 hour: ☐ yes ☒ no
- 5) Inspector Name:

B. GENERAL OUTFALL DESCRIPTION

- 1) Route:
- 2) Milepost:
- 3) Type of Outfall (ex. large cmp, step down box culvert):

Structure

C. FIELD OBSERVATIONS

Flow	Smell	Floatables	Vegetation/ Algae	Deposits
☒ Dry	☒ None	☒ None	☒ None	☒ None
☐ Standing	☐ Musty	☐ Sewage	☐ Minimal	☐ Debris
☐ Slow	☐ Sewage	☐ Oil Sheen	☐ Normal	☐ Sediment
☐ Moderate	☐ Rotten Eggs	☐ Soap Suds	☐ Excessive	☐ Water Line
☐ Fast	☐ Solvent	☐ Other:		☐ Other:
	☐ Chlorine			
	☐ Other:			

NOTE* If any of the above boxes are checked other than Dry or None, a photo must be taken and submitted as Attachment A.

D. ADDITIONAL NOTES

Southeast District, Three-way maintenance unit.

Guthrie Bridge at Gila River, Str #2608

The bridge outfall is located at pipe opening 1510619



A. OUTFALL IDENTIFICATION

- 1) Outfall ID: 1058178
- 2) Date of Inspection: 4/1/2020
- 3) Time of Inspection: 1230
- 4) Rainfall event within the last 72 hour: ☐ yes ☒ no
- 5) Inspector Name: Kent Haugerud

B. GENERAL OUTFALL DESCRIPTION

- 1) Route: I-17
- 2) Milepost: 339.85
- 3) Type of Outfall (ex. large cmp, step down box culvert):

36-in CMP with flared ends

C. FIELD OBSERVATIONS

Flow	Smell	Floatables	Vegetation/ Algae	Deposits
☒ Dry	☒ None	☒ None	☒ None	☐ None
☐ Standing	☐ Musty	☐ Sewage	☐ Minimal	☐ Debris
☐ Slow	☐ Sewage	☐ Oil Sheen	☐ Normal	☒ Sediment
☐ Moderate	☐ Rotten Eggs	☐ Soap Suds	☐ Excessive	☐ Water Line
☐ Fast	☐ Solvent	☐ Other:		☐ Other:
	☐ Chlorine			
	☐ Other:			

NOTE* If any of the above boxes are checked other than Dry or None, a photo must be taken and submitted as Attachment A.

D. ADDITIONAL NOTES

Northcentral District, Little Antelope maintenance unit

Outfall 29
I-17, MP339.85



Photograph 1



Environmental Planning

Dry Weather Field Screening

Site Report Form

A. OUTFALL IDENTIFICATION

- 1) Outfall ID:
- 2) Date of Inspection:
- 3) Time of Inspection:
- 4) Rainfall event within the last 72 hour: ☐ yes ☒ no
- 5) Inspector Name:

B. GENERAL OUTFALL DESCRIPTION

- 1) Route:
- 2) Milepost:
- 3) Type of Outfall (ex. large cmp, step down box culvert):

36-in CMP retrofitted with 20-in HDPE insert

C. FIELD OBSERVATIONS

Flow	Smell	Floatables	Vegetation/ Algae	Deposits
☒ Dry	☒ None	☒ None	☒ None	☒ None
☐ Standing	☐ Musty	☐ Sewage	☐ Minimal	☐ Debris
☐ Slow	☐ Sewage	☐ Oil Sheen	☐ Normal	☐ Sediment
☐ Moderate	☐ Rotten Eggs	☐ Soap Suds	☐ Excessive	☐ Water Line
☐ Fast	☐ Solvent	☐ Other:		☐ Other:
	☐ Chlorine			
	☐ Other:			

NOTE* If any of the above boxes are checked other than Dry or None, a photo must be taken and submitted as Attachment A.

D. ADDITIONAL NOTES

Northcentral District, Little Antelope maintenance unit



Environmental Planning

Dry Weather Field Screening

Site Report Form

A. OUTFALL IDENTIFICATION

- 1) Outfall ID:
- 2) Date of Inspection:
- 3) Time of Inspection:
- 4) Rainfall event within the last 72 hour: ☒ yes ☐ no
- 5) Inspector Name:

B. GENERAL OUTFALL DESCRIPTION

- 1) Route:
- 2) Milepost:
- 3) Type of Outfall (ex. large cmp, step down box culvert):

8-in CMP

C. FIELD OBSERVATIONS

Flow	Smell	Floatables	Vegetation/ Algae	Deposits
☒ Dry	☒ None	☒ None	☒ None	☒ None
☐ Standing	☐ Musty	☐ Sewage	☐ Minimal	☐ Debris
☐ Slow	☐ Sewage	☐ Oil Sheen	☐ Normal	☐ Sediment
☐ Moderate	☐ Rotten Eggs	☐ Soap Suds	☐ Excessive	☐ Water Line
☐ Fast	☐ Solvent	☐ Other:		☐ Other:
	☐ Chlorine			
	☐ Other:			

NOTE* If any of the above boxes are checked other than Dry or None, a photo must be taken and submitted as Attachment A.

D. ADDITIONAL NOTES

Northcentral District, Fredonia maintenance unit
Light drizzle occurring at time of inspection, no runoff observed



A. OUTFALL IDENTIFICATION

- 1) Outfall ID:
- 2) Date of Inspection:
- 3) Time of Inspection:
- 4) Rainfall event within the last 72 hour: ☒ yes ☐ no
- 5) Inspector Name:

B. GENERAL OUTFALL DESCRIPTION

- 1) Route:
- 2) Milepost:
- 3) Type of Outfall (ex. large cmp, step down box culvert):

C. FIELD OBSERVATIONS

Flow

- ☒ Dry
☐ Standing
☐ Slow
☐ Moderate
☐ Fast

Smell

- ☒ None
☐ Musty
☐ Sewage
☐ Rotten Eggs
☐ Solvent
☐ Chlorine
☐ Other:

Floatables

- ☒ None
☐ Sewage
☐ Oil Sheen
☐ Soap Suds
☐ Other:

Vegetation/
Algae

- ☒ None
☐ Minimal
☐ Normal
☐ Excessive

Deposits

- ☒ None
☐ Debris
☐ Sediment
☐ Water Line
☐ Other:

NOTE* If any of the above boxes are checked other than Dry or None, a photo must be taken and submitted as Attachment A.

D. ADDITIONAL NOTES

Northcentral District, Fredonia maintenance unit
Light drizzle occurring at time of inspection, no runoff observed



A. OUTFALL IDENTIFICATION

- 1) Outfall ID: 1069545
- 2) Date of Inspection: 3/10/2020
- 3) Time of Inspection: 9:30 am
- 4) Rainfall event within the last 72 hour: ☒ yes ☐ no
- 5) Inspector Name: Laura Nordan

B. GENERAL OUTFALL DESCRIPTION

- 1) Route: I-15 NB
- 2) Milepost: 9.35
- 3) Type of Outfall (ex. large cmp, step down box culvert):

12-in CMP

C. FIELD OBSERVATIONS

Flow

- ☒ Dry
☐ Standing
☐ Slow
☐ Moderate
☐ Fast

Smell

- ☒ None
☐ Musty
☐ Sewage
☐ Rotten Eggs
☐ Solvent
☐ Chlorine
☐ Other:

Floatables

- ☒ None
☐ Sewage
☐ Oil Sheen
☐ Soap Suds
☐ Other:

Vegetation/
Algae

- ☐ None
☒ Minimal
☐ Normal
☐ Excessive

Deposits

- ☒ None
☐ Debris
☐ Sediment
☐ Water Line
☐ Other:

NOTE* If any of the above boxes are checked other than Dry or None, a photo must be taken and submitted as Attachment A.

D. ADDITIONAL NOTES

Northcentral District, Fredonia maintenance unit
Light drizzle occurring at time of inspection, no runoff observed

ATTACHMENT A
Photo Documentation of Flows



Outfall ID: 1069545

Permit Year 2020



Environmental Planning

Dry Weather Field Screening

Site Report Form

A. OUTFALL IDENTIFICATION

- 1) Outfall ID:
- 2) Date of Inspection:
- 3) Time of Inspection:
- 4) Rainfall event within the last 72 hour: ☒ yes ☐ no
- 5) Inspector Name:

B. GENERAL OUTFALL DESCRIPTION

- 1) Route:
- 2) Milepost:
- 3) Type of Outfall (ex. large cmp, step down box culvert):

8-in CMP

C. FIELD OBSERVATIONS

Flow	Smell	Floatables	Vegetation/ Algae	Deposits
☒ Dry	☒ None	☒ None	☒ None	☒ None
☐ Standing	☐ Musty	☐ Sewage	☐ Minimal	☐ Debris
☐ Slow	☐ Sewage	☐ Oil Sheen	☐ Normal	☐ Sediment
☐ Moderate	☐ Rotten Eggs	☐ Soap Suds	☒ Excessive	☐ Water Line
☐ Fast	☐ Solvent	☐ Other:		☐ Other:
	☐ Chlorine			
	☐ Other:			

NOTE* If any of the above boxes are checked other than Dry or None, a photo must be taken and submitted as Attachment A.

D. ADDITIONAL NOTES

Northcentral District, Fredonia maintenance unit
Light drizzle occurring at time of inspection, no runoff observed

ATTACHMENT A
Photo Documentation of Flows



Outfall ID: 1069546

Permit Year 2020



Environmental Planning

Dry Weather Field Screening

Site Report Form

A. OUTFALL IDENTIFICATION

- 1) Outfall ID:
- 2) Date of Inspection:
- 3) Time of Inspection:
- 4) Rainfall event within the last 72 hour: ☒ yes ☐ no
- 5) Inspector Name:

B. GENERAL OUTFALL DESCRIPTION

- 1) Route:
- 2) Milepost:
- 3) Type of Outfall (ex. large cmp, step down box culvert):

8-in CMP

C. FIELD OBSERVATIONS

Flow	Smell	Floatables	Vegetation/ Algae	Deposits
☒ Dry	☒ None	☒ None	☒ None	☒ None
☐ Standing	☐ Musty	☐ Sewage	☐ Minimal	☐ Debris
☐ Slow	☐ Sewage	☐ Oil Sheen	☒ Normal	☐ Sediment
☐ Moderate	☐ Rotten Eggs	☐ Soap Suds	☐ Excessive	☐ Water Line
☐ Fast	☐ Solvent	☐ Other:		☐ Other:
	☐ Chlorine			
	☐ Other:			

NOTE* If any of the above boxes are checked other than Dry or None, a photo must be taken and submitted as Attachment A.

D. ADDITIONAL NOTES

Northcentral District, Fredonia maintenance unit
Light drizzle occurring at time of inspection, no runoff observed

ATTACHMENT A
Photo Documentation of Flows



Outfall ID:

1069547

Permit Year 2020



Environmental Planning

Dry Weather Field Screening

Site Report Form

A. OUTFALL IDENTIFICATION

- 1) Outfall ID:
- 2) Date of Inspection:
- 3) Time of Inspection:
- 4) Rainfall event within the last 72 hour: ☒ yes ☐ no
- 5) Inspector Name:

B. GENERAL OUTFALL DESCRIPTION

- 1) Route:
- 2) Milepost:
- 3) Type of Outfall (ex. large cmp, step down box culvert):

8-in CMP

C. FIELD OBSERVATIONS

Flow	Smell	Floatables	Vegetation/ Algae	Deposits
☒ Dry	☒ None	☒ None	☒ None	☒ None
☐ Standing	☐ Musty	☐ Sewage	☐ Minimal	☐ Debris
☐ Slow	☐ Sewage	☐ Oil Sheen	☒ Normal	☐ Sediment
☐ Moderate	☐ Rotten Eggs	☐ Soap Suds	☐ Excessive	☐ Water Line
☐ Fast	☐ Solvent	☐ Other:		☐ Other:
	☐ Chlorine			
	☐ Other:			

NOTE* If any of the above boxes are checked other than Dry or None, a photo must be taken and submitted as Attachment A.

D. ADDITIONAL NOTES

Northcentral District, Fredonia maintenance unit
Light drizzle occurring at time of inspection, no runoff observed

ATTACHMENT A
Photo Documentation of Flows



Outfall ID: 1069548

Permit Year 2020



A. OUTFALL IDENTIFICATION

- 1) Outfall ID: 1069550
- 2) Date of Inspection: 3/10/2020
- 3) Time of Inspection: 9:15 am
- 4) Rainfall event within the last 72 hour: ☒ yes ☐ no
- 5) Inspector Name: Laura Nordan

B. GENERAL OUTFALL DESCRIPTION

- 1) Route: I-15 NB
- 2) Milepost: 9.46
- 3) Type of Outfall (ex. large cmp, step down box culvert):

8-in CMP

C. FIELD OBSERVATIONS

Flow	Smell	Floatables	Vegetation/ Algae	Deposits
☒ Dry	☒ None	☒ None	☒ None	☒ None
☐ Standing	☐ Musty	☐ Sewage	☐ Minimal	☐ Debris
☐ Slow	☐ Sewage	☐ Oil Sheen	☒ Normal	☐ Sediment
☐ Moderate	☐ Rotten Eggs	☐ Soap Suds	☐ Excessive	☐ Water Line
☐ Fast	☐ Solvent	☐ Other:		☐ Other:
	☐ Chlorine			
	☐ Other:			

NOTE* If any of the above boxes are checked other than Dry or None, a photo must be taken and submitted as Attachment A.

D. ADDITIONAL NOTES

Northcentral District, Fredonia maintenance unit
Light drizzle occurring at time of inspection, no runoff observed

ATTACHMENT A
Photo Documentation of Flows



Outfall ID: 1069550

Permit Year 2020



A. OUTFALL IDENTIFICATION

- 1) Outfall ID:
- 2) Date of Inspection:
- 3) Time of Inspection:
- 4) Rainfall event within the last 72 hour: ☐ yes ☒ no
- 5) Inspector Name:

B. GENERAL OUTFALL DESCRIPTION

- 1) Route:
- 2) Milepost:
- 3) Type of Outfall (ex. large cmp, step down box culvert):

C. FIELD OBSERVATIONS

Flow

- ☒ Dry
☐ Standing
☐ Slow
☐ Moderate
☐ Fast

Smell

- ☒ None
☐ Musty
☐ Sewage
☐ Rotten Eggs
☐ Solvent
☐ Chlorine
☐ Other:

Floatables

- ☒ None
☐ Sewage
☐ Oil Sheen
☐ Soap Suds
☐ Other:

Vegetation/
Algae

- ☐ None
☐ Minimal
☐ Normal
☒ Excessive

Deposits

- ☐ None
☒ Debris
☒ Sediment
☐ Water Line
☐ Other:

NOTE* If any of the above boxes are checked other than Dry or None, a photo must be taken and submitted as Attachment A.

D. ADDITIONAL NOTES

ATTACHMENT A
Photo Documentation of Flows



Outfall ID: 1485571

Permit Year 2020



A. OUTFALL IDENTIFICATION

- 1) Outfall ID: 1486080
- 2) Date of Inspection: 3/31/2020
- 3) Time of Inspection: 1:54 pm
- 4) Rainfall event within the last 72 hour: ☐ yes ☒ no
- 5) Inspector Name: Laura Nordan

B. GENERAL OUTFALL DESCRIPTION

- 1) Route: SR 89 NB
- 2) Milepost: 306.33
- 3) Type of Outfall (ex. large cmp, step down box culvert):

Spillway

C. FIELD OBSERVATIONS

Flow

- ☒ Dry
☐ Standing
☐ Slow
☐ Moderate
☐ Fast

Smell

- ☒ None
☐ Musty
☐ Sewage
☐ Rotten Eggs
☐ Solvent
☐ Chlorine
☐ Other:

Floatables

- ☒ None
☐ Sewage
☐ Oil Sheen
☐ Soap Suds
☐ Other:

Vegetation/
Algae

- ☒ None
☐ Minimal
☐ Normal
☐ Excessive

Deposits

- ☐ None
☒ Debris
☐ Sediment
☐ Water Line
☐ Other:

NOTE* If any of the above boxes are checked other than Dry or None, a photo must be taken and submitted as Attachment A.

D. ADDITIONAL NOTES

Northwest District, Prescott maintenance unit

ATTACHMENT A
Photo Documentation of Flows



Outfall ID: 1486080

Permit Year 2020



A. OUTFALL IDENTIFICATION

- 1) Outfall ID:
- 2) Date of Inspection:
- 3) Time of Inspection:
- 4) Rainfall event within the last 72 hour: ☐ yes ☒ no
- 5) Inspector Name:

B. GENERAL OUTFALL DESCRIPTION

- 1) Route:
- 2) Milepost:
- 3) Type of Outfall (ex. large cmp, step down box culvert):

C. FIELD OBSERVATIONS

Flow

- ☒ Dry
☐ Standing
☐ Slow
☐ Moderate
☐ Fast

Smell

- ☒ None
☐ Musty
☐ Sewage
☐ Rotten Eggs
☐ Solvent
☐ Chlorine
☐ Other:

Floatables

- ☒ None
☐ Sewage
☐ Oil Sheen
☐ Soap Suds
☐ Other:

Vegetation/
Algae

- ☐ None
☐ Minimal
☒ Normal
☐ Excessive

Deposits

- ☐ None
☒ Debris
☐ Sediment
☐ Water Line
☐ Other:

NOTE* If any of the above boxes are checked other than Dry or None, a photo must be taken and submitted as Attachment A.

D. ADDITIONAL NOTES

ATTACHMENT A
Photo Documentation of Flows



Outfall ID:

1486083

Permit Year 2020



A. OUTFALL IDENTIFICATION

- 1) Outfall ID: 1488480
- 2) Date of Inspection: 4/1/2020
- 3) Time of Inspection: 8:20 am
- 4) Rainfall event within the last 72 hour: ☐ yes ☒ no
- 5) Inspector Name: Laura Nordan

B. GENERAL OUTFALL DESCRIPTION

- 1) Route: SR 69 EB
- 2) Milepost: 287.98
- 3) Type of Outfall (ex. large cmp, step down box culvert):

42-in CMP

C. FIELD OBSERVATIONS

Flow	Smell	Floatables	Vegetation/ Algae	Deposits
☒ Dry	☒ None	☒ None	☒ None	☐ None
☐ Standing	☐ Musty	☐ Sewage	☐ Minimal	☐ Debris
☐ Slow	☐ Sewage	☐ Oil Sheen	☐ Normal	☐ Sediment
☐ Moderate	☐ Rotten Eggs	☐ Soap Suds	☐ Excessive	☒ Water Line
☐ Fast	☐ Solvent	☐ Other:		☐ Other:
	☐ Chlorine			
	☐ Other:			

NOTE* If any of the above boxes are checked other than Dry or None, a photo must be taken and submitted as Attachment A.

D. ADDITIONAL NOTES

Northwest District, Prescott maintenance unit

ATTACHMENT A
Photo Documentation of Flows



Outfall ID: 1488480

Permit Year 2020



A. OUTFALL IDENTIFICATION

- 1) Outfall ID: 1510550
- 2) Date of Inspection: 3/18/2020
- 3) Time of Inspection: 9:30 am
- 4) Rainfall event within the last 72 hour: ☐ yes ☒ no
- 5) Inspector Name: Laura Nordan and Michael Carlson

B. GENERAL OUTFALL DESCRIPTION

- 1) Route: SR 77 NB
- 2) Milepost: 79.84
- 3) Type of Outfall (ex. large cmp, step down box culvert):

Concrete lined channel, 5' deep, 12' wide at bottom

C. FIELD OBSERVATIONS

Flow	Smell	Floatables	Vegetation/ Algae	Deposits
☒ Dry	☒ None	☒ None	☐ None	☐ None
☐ Standing	☐ Musty	☐ Sewage	☐ Minimal	☒ Debris
☐ Slow	☐ Sewage	☐ Oil Sheen	☐ Normal	☒ Sediment
☐ Moderate	☐ Rotten Eggs	☐ Soap Suds	☒ Excessive	☐ Water Line
☐ Fast	☐ Solvent	☐ Other:		☐ Other:
	☐ Chlorine			
	☐ Other:			

NOTE* If any of the above boxes are checked other than Dry or None, a photo must be taken and submitted as Attachment A.

D. ADDITIONAL NOTES

Southcentral District, Tucson East maintenance unit

ATTACHMENT A
Photo Documentation of Flows



Outfall ID: 1510550

Permit Year 2020



A. OUTFALL IDENTIFICATION

- 1) Outfall ID: 1510619
- 2) Date of Inspection: 3/17/2020
- 3) Time of Inspection: 11:10 am
- 4) Rainfall event within the last 72 hour: ☐ yes ☒ no
- 5) Inspector Name: Laura Nordan and Matt Holcombe

B. GENERAL OUTFALL DESCRIPTION

- 1) Route: US 191
- 2) Milepost: 153.43
- 3) Type of Outfall (ex. large cmp, step down box culvert):

24-in CMP

C. FIELD OBSERVATIONS

Flow

- ☐ Dry
☒ Standing
☐ Slow
☐ Moderate
☐ Fast

Smell

- ☒ None
☐ Musty
☐ Sewage
☐ Rotten Eggs
☐ Solvent
☐ Chlorine
☐ Other:

Floatables

- ☒ None
☐ Sewage
☐ Oil Sheen
☐ Soap Suds
☐ Other:

Vegetation/
Algae

- ☒ None
☐ Minimal
☐ Normal
☐ Excessive

Deposits

- ☐ None
☒ Debris
☒ Sediment
☐ Water Line
☐ Other:

NOTE* If any of the above boxes are checked other than Dry or None, a photo must be taken and submitted as Attachment A.

D. ADDITIONAL NOTES

Southeast District, Three-way maintenance unit

ATTACHMENT A
Photo Documentation of Flows



Outfall ID: 1510619

Permit Year 2020



Environmental Planning

Dry Weather Field Screening

Site Report Form

A. OUTFALL IDENTIFICATION

- 1) Outfall ID:
- 2) Date of Inspection:
- 3) Time of Inspection:
- 4) Rainfall event within the last 72 hour: ☐ yes ☒ no
- 5) Inspector Name:

B. GENERAL OUTFALL DESCRIPTION

- 1) Route:
- 2) Milepost:
- 3) Type of Outfall (ex. large cmp, step down box culvert):

36-in Concrete pipe

C. FIELD OBSERVATIONS

Flow	Smell	Floatables	Vegetation/ Algae	Deposits
☒ Dry	☒ None	☒ None	☐ None	☐ None
☐ Standing	☐ Musty	☐ Sewage	☐ Minimal	☒ Debris
☐ Slow	☐ Sewage	☐ Oil Sheen	☒ Normal	☒ Sediment
☐ Moderate	☐ Rotten Eggs	☐ Soap Suds	☐ Excessive	☐ Water Line
☐ Fast	☐ Solvent	☐ Other:		☐ Other:
	☐ Chlorine			
	☐ Other:			

NOTE* If any of the above boxes are checked other than Dry or None, a photo must be taken and submitted as Attachment A.

D. ADDITIONAL NOTES

Central District, University maintenance unit

ATTACHMENT A
Photo Documentation of Flows



Outfall ID: 1512473

Permit Year 2020



A. OUTFALL IDENTIFICATION

- 1) Outfall ID: 1512474
- 2) Date of Inspection: 3/5/2020
- 3) Time of Inspection: 11:00 am
- 4) Rainfall event within the last 72 hour: ☐ yes ☒ no
- 5) Inspector Name: Laura Nordan and Alexis Zaring

B. GENERAL OUTFALL DESCRIPTION

- 1) Route: SR 202 EB
- 2) Milepost: 7.99
- 3) Type of Outfall (ex. large cmp, step down box culvert):

8x8x2 CBC

C. FIELD OBSERVATIONS

Flow

- ☐ Dry
☒ Standing
☐ Slow
☐ Moderate
☐ Fast

Smell

- ☒ None
☐ Musty
☐ Sewage
☐ Rotten Eggs
☐ Solvent
☐ Chlorine
☐ Other:

Floatables

- ☒ None
☐ Sewage
☐ Oil Sheen
☐ Soap Suds
☐ Other:

Vegetation/
Algae

- ☒ None
☐ Minimal
☐ Normal
☐ Excessive

Deposits

- ☒ None
☐ Debris
☐ Sediment
☐ Water Line
☐ Other:

NOTE* If any of the above boxes are checked other than Dry or None, a photo must be taken and submitted as Attachment A.

D. ADDITIONAL NOTES

Central District, University maintenance unit

Outfall submerged in Tempe Town Lake

ATTACHMENT A
Photo Documentation of Flows



Outfall ID: 1512474

Permit Year 2020



A. OUTFALL IDENTIFICATION

- 1) Outfall ID: 1512475
- 2) Date of Inspection: 2/18/2020
- 3) Time of Inspection: 1:52 pm
- 4) Rainfall event within the last 72 hour: ☐ yes ☒ no
- 5) Inspector Name: Laura Nordan and Alexis Zaring

B. GENERAL OUTFALL DESCRIPTION

- 1) Route: SR 202
- 2) Milepost: 8.30
- 3) Type of Outfall (ex. large cmp, step down box culvert):

Pipe 48-inch diameter

C. FIELD OBSERVATIONS

Flow	Smell	Floatables	Vegetation/ Algae	Deposits
☒ Dry	☒ None	☒ None	☒ None	☐ None
☐ Standing	☐ Musty	☐ Sewage	☐ Minimal	☒ Debris
☐ Slow	☐ Sewage	☐ Oil Sheen	☐ Normal	☐ Sediment
☐ Moderate	☐ Rotten Eggs	☐ Soap Suds	☐ Excessive	☐ Water Line
☐ Fast	☐ Solvent	☐ Other:		☐ Other:
	☐ Chlorine			
	☐ Other:			

NOTE* If any of the above boxes are checked other than Dry or None, a photo must be taken and submitted as Attachment A.

D. ADDITIONAL NOTES

Central District, University maintenance unit

ATTACHMENT A
Photo Documentation of Flows



Outfall ID: 1512475

Permit Year 2020



A. OUTFALL IDENTIFICATION

- 1) Outfall ID: 1512476
- 2) Date of Inspection: 2/18/2020
- 3) Time of Inspection: 2:00 pm
- 4) Rainfall event within the last 72 hour: ☐ yes ☒ no
- 5) Inspector Name: Laura Nordan and Alexis Zaring

B. GENERAL OUTFALL DESCRIPTION

- 1) Route: SR 202
- 2) Milepost: 8.45
- 3) Type of Outfall (ex. large cmp, step down box culvert):

Pipe 24-inch diameter

C. FIELD OBSERVATIONS

Flow	Smell	Floatables	Vegetation/ Algae	Deposits
☐ Dry	☒ None	☒ None	☒ None	☒ None
☒ Standing	☐ Musty	☐ Sewage	☐ Minimal	☐ Debris
☐ Slow	☐ Sewage	☐ Oil Sheen	☐ Normal	☐ Sediment
☐ Moderate	☐ Rotten Eggs	☐ Soap Suds	☒ Excessive	☐ Water Line
☐ Fast	☐ Solvent	☐ Other:		☐ Other:
	☐ Chlorine			
	☐ Other:			

NOTE* If any of the above boxes are checked other than Dry or None, a photo must be taken and submitted as Attachment A.

D. ADDITIONAL NOTES

Central District, University maintenance unit

Pipe opening partially submerged by lake

ATTACHMENT A
Photo Documentation of Flows



Outfall ID: 1512476

Permit Year 2020



A. OUTFALL IDENTIFICATION

- 1) Outfall ID: 1512477
- 2) Date of Inspection: 2/18/2020
- 3) Time of Inspection: 11:15 am
- 4) Rainfall event within the last 72 hour: ☐ yes ☒ no
- 5) Inspector Name: Laura Nordan and Alexis Zaring

B. GENERAL OUTFALL DESCRIPTION

- 1) Route: SR 202
- 2) Milepost: 14.45
- 3) Type of Outfall (ex. large cmp, step down box culvert):

Concrete-lined channel

C. FIELD OBSERVATIONS

Flow	Smell	Floatables	Vegetation/ Algae	Deposits
☒ Dry	☒ None	☒ None	☒ None	☒ None
☐ Standing	☐ Musty	☐ Sewage	☐ Minimal	☐ Debris
☐ Slow	☐ Sewage	☐ Oil Sheen	☐ Normal	☐ Sediment
☐ Moderate	☐ Rotten Eggs	☐ Soap Suds	☐ Excessive	☐ Water Line
☐ Fast	☐ Solvent	☐ Other:		☐ Other:
	☐ Chlorine			
	☐ Other:			

NOTE* If any of the above boxes are checked other than Dry or None, a photo must be taken and submitted as Attachment A.

D. ADDITIONAL NOTES

Central District, Mesa maintenance unit



A. OUTFALL IDENTIFICATION

- 1) Outfall ID: 1512486
- 2) Date of Inspection: 2/18/2020
- 3) Time of Inspection: 1:15 pm
- 4) Rainfall event within the last 72 hour: ☐ yes ☒ no
- 5) Inspector Name: Laura Nordan and Alexis Zaring

B. GENERAL OUTFALL DESCRIPTION

- 1) Route: SR 101
- 2) Milepost: 51.38
- 3) Type of Outfall (ex. large cmp, step down box culvert):

CBC 10x10x2

C. FIELD OBSERVATIONS

Flow

- ☐ Dry
☒ Standing
☐ Slow
☐ Moderate
☐ Fast

Smell

- ☒ None
☐ Musty
☐ Sewage
☐ Rotten Eggs
☐ Solvent
☐ Chlorine
☐ Other:

Floatables

- ☒ None
☐ Sewage
☐ Oil Sheen
☐ Soap Suds
☐ Other:

Vegetation/
Algae

- ☐ None
☐ Minimal
☐ Normal
☒ Excessive

Deposits

- ☐ None
☒ Debris
☒ Sediment
☐ Water Line
☐ Other:

NOTE* If any of the above boxes are checked other than Dry or None, a photo must be taken and submitted as Attachment A.

D. ADDITIONAL NOTES

Central District, University maintenance unit

ATTACHMENT A
Photo Documentation of Flows



Outfall ID: 1512486

Permit Year 2020



A. OUTFALL IDENTIFICATION

- 1) Outfall ID:
- 2) Date of Inspection:
- 3) Time of Inspection:
- 4) Rainfall event within the last 72 hour: ☐ yes ☒ no
- 5) Inspector Name:

B. GENERAL OUTFALL DESCRIPTION

- 1) Route:
- 2) Milepost:
- 3) Type of Outfall (ex. large cmp, step down box culvert):

C. FIELD OBSERVATIONS

Flow

- ☐ Dry
☐ Standing
☐ Slow
☒ Moderate
☐ Fast

Smell

- ☒ None
☐ Musty
☐ Sewage
☐ Rotten Eggs
☐ Solvent
☐ Chlorine
☐ Other:

Floatables

- ☐ None
☐ Sewage
☐ Oil Sheen
☒ Soap Suds
☐ Other:

Vegetation/
Algae

- ☐ None
☐ Minimal
☐ Normal
☒ Excessive

Deposits

- ☐ None
☐ Debris
☒ Sediment
☐ Water Line
☐ Other:

NOTE* If any of the above boxes are checked other than Dry or None, a photo must be taken and submitted as Attachment A.

D. ADDITIONAL NOTES

ATTACHMENT A
Photo Documentation of Flows



Outfall ID: 1512487

Permit Year 2020



Environmental Planning

Dry Weather Field Screening

Site Report Form

A. OUTFALL IDENTIFICATION

- 1) Outfall ID:
- 2) Date of Inspection:
- 3) Time of Inspection:
- 4) Rainfall event within the last 72 hour: ☐ yes ☒ no
- 5) Inspector Name:

B. GENERAL OUTFALL DESCRIPTION

- 1) Route:
- 2) Milepost:
- 3) Type of Outfall (ex. large cmp, step down box culvert):

Pipe 48-inch diameter

C. FIELD OBSERVATIONS

Flow	Smell	Floatables	Vegetation/ Algae	Deposits
☒ Dry	☒ None	☒ None	☒ None	☒ None
☐ Standing	☐ Musty	☐ Sewage	☐ Minimal	☐ Debris
☐ Slow	☐ Sewage	☐ Oil Sheen	☐ Normal	☐ Sediment
☐ Moderate	☐ Rotten Eggs	☐ Soap Suds	☒ Excessive	☐ Water Line
☐ Fast	☐ Solvent	☐ Other:		☐ Other:
	☐ Chlorine			
	☐ Other:			

NOTE* If any of the above boxes are checked other than Dry or None, a photo must be taken and submitted as Attachment A.

D. ADDITIONAL NOTES

Central District, Durango maintenance unit

ATTACHMENT A
Photo Documentation of Flows



Outfall ID: 1512537

Permit Year 2020



A. OUTFALL IDENTIFICATION

- 1) Outfall ID: 1512540
- 2) Date of Inspection: 2/7/2020
- 3) Time of Inspection: 10:15 am
- 4) Rainfall event within the last 72 hour: ☐ yes ☒ no
- 5) Inspector Name: Laura Nordan and Alexis Zaring

B. GENERAL OUTFALL DESCRIPTION

- 1) Route: SR 51
- 2) Milepost: 11.04
- 3) Type of Outfall (ex. large cmp, step down box culvert):

CBC 9x12x3

C. FIELD OBSERVATIONS

Flow	Smell	Floatables	Vegetation/ Algae	Deposits
☒ Dry	☒ None	☒ None	☐ None	☐ None
☐ Standing	☐ Musty	☐ Sewage	☐ Minimal	☒ Debris
☐ Slow	☐ Sewage	☐ Oil Sheen	☒ Normal	☒ Sediment
☐ Moderate	☐ Rotten Eggs	☐ Soap Suds	☐ Excessive	☐ Water Line
☐ Fast	☐ Solvent	☐ Other:		☐ Other:
	☐ Chlorine			
	☐ Other:			

NOTE* If any of the above boxes are checked other than Dry or None, a photo must be taken and submitted as Attachment A.

D. ADDITIONAL NOTES

Central District, Happy Valley maintenance unit

ATTACHMENT A
Photo Documentation of Flows



Outfall ID: 1512540

Permit Year 2020



A. OUTFALL IDENTIFICATION

- 1) Outfall ID: 1512541
- 2) Date of Inspection: 2/7/2020
- 3) Time of Inspection: 10:30 am
- 4) Rainfall event within the last 72 hour: ☐ yes ☒ no
- 5) Inspector Name: Laura Nordan and Alexis Zaring

B. GENERAL OUTFALL DESCRIPTION

- 1) Route: SR 51
- 2) Milepost: 11.63
- 3) Type of Outfall (ex. large cmp, step down box culvert):

CBC 6x10x1

C. FIELD OBSERVATIONS

Flow	Smell	Floatables	Vegetation/ Algae	Deposits
☒ Dry	☒ None	☒ None	☒ None	☒ None
☐ Standing	☐ Musty	☐ Sewage	☐ Minimal	☐ Debris
☐ Slow	☐ Sewage	☐ Oil Sheen	☐ Normal	☐ Sediment
☐ Moderate	☐ Rotten Eggs	☐ Soap Suds	☐ Excessive	☐ Water Line
☐ Fast	☐ Solvent	☐ Other:		☐ Other:
	☐ Chlorine			
	☐ Other:			

NOTE* If any of the above boxes are checked other than Dry or None, a photo must be taken and submitted as Attachment A.

D. ADDITIONAL NOTES

Central District, Happy Valley maintenance unit



A. OUTFALL IDENTIFICATION

- 1) Outfall ID: 1512542
- 2) Date of Inspection: 2/7/2020
- 3) Time of Inspection: 10:30 am
- 4) Rainfall event within the last 72 hour: ☐ yes ☒ no
- 5) Inspector Name: Laura Nordan and Alexis Zaring

B. GENERAL OUTFALL DESCRIPTION

- 1) Route: SR 51
- 2) Milepost: 11.63
- 3) Type of Outfall (ex. large cmp, step down box culvert):

CMP 84-in

C. FIELD OBSERVATIONS

Flow

- ☒ Dry
☐ Standing
☐ Slow
☐ Moderate
☐ Fast

Smell

- ☒ None
☐ Musty
☐ Sewage
☐ Rotten Eggs
☐ Solvent
☐ Chlorine
☐ Other:

Floatables

- ☒ None
☐ Sewage
☐ Oil Sheen
☐ Soap Suds
☐ Other:

Vegetation/
Algae

- ☒ None
☐ Minimal
☐ Normal
☐ Excessive

Deposits

- ☐ None
☒ Debris
☐ Sediment
☒ Water Line
☐ Other:

NOTE* If any of the above boxes are checked other than Dry or None, a photo must be taken and submitted as Attachment A.

D. ADDITIONAL NOTES

Central District, Happy Valley maintenance unit

ATTACHMENT A
Photo Documentation of Flows



Outfall ID: 1512542

Permit Year 2020



A. OUTFALL IDENTIFICATION

- 1) Outfall ID: 1512544
- 2) Date of Inspection: 2/19/2020
- 3) Time of Inspection: 12:45 pm
- 4) Rainfall event within the last 72 hour: ☐ yes ☒ no
- 5) Inspector Name: Laura Nordan and Alexis Zaring

B. GENERAL OUTFALL DESCRIPTION

- 1) Route: I-17
- 2) Milepost: 208.84
- 3) Type of Outfall (ex. large cmp, step down box culvert):

Catch basin outlet, 36-inch

C. FIELD OBSERVATIONS

Flow	Smell	Floatables	Vegetation/ Algae	Deposits
☒ Dry	☒ None	☒ None	☒ None	☐ None
☐ Standing	☐ Musty	☐ Sewage	☐ Minimal	☐ Debris
☐ Slow	☐ Sewage	☐ Oil Sheen	☐ Normal	☒ Sediment
☐ Moderate	☐ Rotten Eggs	☐ Soap Suds	☐ Excessive	☐ Water Line
☐ Fast	☐ Solvent	☐ Other:		☐ Other:
	☐ Chlorine			
	☐ Other:			

NOTE* If any of the above boxes are checked other than Dry or None, a photo must be taken and submitted as Attachment A.

D. ADDITIONAL NOTES

Central District, Durango maintenance unit

Construction in progress at this outfall at time of inspection

ATTACHMENT A
Photo Documentation of Flows



Outfall ID: 1512544

Permit Year 2020



Environmental Planning

Dry Weather Field Screening

Site Report Form

A. OUTFALL IDENTIFICATION

- 1) Outfall ID:
- 2) Date of Inspection:
- 3) Time of Inspection:
- 4) Rainfall event within the last 72 hour: ☐ yes ☒ no
- 5) Inspector Name:

B. GENERAL OUTFALL DESCRIPTION

- 1) Route:
- 2) Milepost:
- 3) Type of Outfall (ex. large cmp, step down box culvert):

CBC 6x8x2

C. FIELD OBSERVATIONS

Flow	Smell	Floatables	Vegetation/ Algae	Deposits
☒ Dry	☒ None	☒ None	☒ None	☐ None
☐ Standing	☐ Musty	☐ Sewage	☐ Minimal	☒ Debris
☐ Slow	☐ Sewage	☐ Oil Sheen	☐ Normal	☒ Sediment
☐ Moderate	☐ Rotten Eggs	☐ Soap Suds	☐ Excessive	☐ Water Line
☐ Fast	☐ Solvent	☐ Other:		☐ Other:
	☐ Chlorine			
	☐ Other:			

NOTE* If any of the above boxes are checked other than Dry or None, a photo must be taken and submitted as Attachment A.

D. ADDITIONAL NOTES

Central District, Happy Valley maintenance unit

ATTACHMENT A
Photo Documentation of Flows



Outfall ID: 1512546

Permit Year 2020



A. OUTFALL IDENTIFICATION

- 1) Outfall ID: 1512547
- 2) Date of Inspection: 2/7/2020
- 3) Time of Inspection: 11:24 am
- 4) Rainfall event within the last 72 hour: ☐ yes ☒ no
- 5) Inspector Name: Laura Nordan and Alexis Zaring

B. GENERAL OUTFALL DESCRIPTION

- 1) Route: SR 101
- 2) Milepost: 21.87
- 3) Type of Outfall (ex. large cmp, step down box culvert):

Pipe opening - 42-in

C. FIELD OBSERVATIONS

Flow	Smell	Floatables	Vegetation/ Algae	Deposits
☒ Dry	☒ None	☒ None	☒ None	☐ None
☐ Standing	☐ Musty	☐ Sewage	☐ Minimal	☐ Debris
☐ Slow	☐ Sewage	☐ Oil Sheen	☐ Normal	☐ Sediment
☐ Moderate	☐ Rotten Eggs	☐ Soap Suds	☐ Excessive	☒ Water Line
☐ Fast	☐ Solvent	☐ Other:		☐ Other:
	☐ Chlorine			
	☐ Other:			

NOTE* If any of the above boxes are checked other than Dry or None, a photo must be taken and submitted as Attachment A.

D. ADDITIONAL NOTES

Central District, Happy Valley maintenance unit

ATTACHMENT A
Photo Documentation of Flows



Outfall ID: 1512547

Permit Year 2020



Environmental Planning

Dry Weather Field Screening

Site Report Form

A. OUTFALL IDENTIFICATION

- 1) Outfall ID:
- 2) Date of Inspection:
- 3) Time of Inspection:
- 4) Rainfall event within the last 72 hour: ☐ yes ☒ no
- 5) Inspector Name:

B. GENERAL OUTFALL DESCRIPTION

- 1) Route:
- 2) Milepost:
- 3) Type of Outfall (ex. large cmp, step down box culvert):

Concrete pipe opening - 96-in

C. FIELD OBSERVATIONS

Flow

- ☒ Dry
☐ Standing
☐ Slow
☐ Moderate
☐ Fast

Smell

- ☒ None
☐ Musty
☐ Sewage
☐ Rotten Eggs
☐ Solvent
☐ Chlorine
☐ Other:

Floatables

- ☒ None
☐ Sewage
☐ Oil Sheen
☐ Soap Suds
☐ Other:

Vegetation/ Algae

- ☒ None
☐ Minimal
☐ Normal
☐ Excessive

Deposits

- ☐ None
☒ Debris
☒ Sediment
☐ Water Line
☐ Other:

NOTE* If any of the above boxes are checked other than Dry or None, a photo must be taken and submitted as Attachment A.

D. ADDITIONAL NOTES

Central District, Happy Valley maintenance unit

ATTACHMENT A
Photo Documentation of Flows



Outfall ID: 1512548

Permit Year 2020



Environmental Planning

Dry Weather Field Screening

Site Report Form

A. OUTFALL IDENTIFICATION

- 1) Outfall ID:
- 2) Date of Inspection:
- 3) Time of Inspection:
- 4) Rainfall event within the last 72 hour: ☐ yes ☒ no
- 5) Inspector Name:

B. GENERAL OUTFALL DESCRIPTION

- 1) Route:
- 2) Milepost:
- 3) Type of Outfall (ex. large cmp, step down box culvert):

Concrete-lined channel

C. FIELD OBSERVATIONS

Flow

- ☒ Dry
☐ Standing
☐ Slow
☐ Moderate
☐ Fast

Smell

- ☒ None
☐ Musty
☐ Sewage
☐ Rotten Eggs
☐ Solvent
☐ Chlorine
☐ Other:

Floatables

- ☒ None
☐ Sewage
☐ Oil Sheen
☐ Soap Suds
☐ Other:

Vegetation/ Algae

- ☒ None
☐ Minimal
☐ Normal
☐ Excessive

Deposits

- ☐ None
☒ Debris
☐ Sediment
☐ Water Line
☒ Other:

Dumping

NOTE* If any of the above boxes are checked other than Dry or None, a photo must be taken and submitted as Attachment A.

D. ADDITIONAL NOTES

Central District, Happy Valley maintenance unit

ATTACHMENT A
Photo Documentation of Flows



Outfall ID: 1512549

Permit Year 2020



A. OUTFALL IDENTIFICATION

- 1) Outfall ID: 1512550
- 2) Date of Inspection: 2/7/2020
- 3) Time of Inspection: 11:40 am
- 4) Rainfall event within the last 72 hour: ☐ yes ☒ no
- 5) Inspector Name: Laura Nordan and Alexis Zaring

B. GENERAL OUTFALL DESCRIPTION

- 1) Route: SR 101
- 2) Milepost: 21.24
- 3) Type of Outfall (ex. large cmp, step down box culvert):

Concrete pipe opening - 42-in

C. FIELD OBSERVATIONS

Flow	Smell	Floatables	Vegetation/ Algae	Deposits
☒ Dry	☒ None	☒ None	☒ None	☐ None
☐ Standing	☐ Musty	☐ Sewage	☐ Minimal	☐ Debris
☐ Slow	☐ Sewage	☐ Oil Sheen	☐ Normal	☐ Sediment
☐ Moderate	☐ Rotten Eggs	☐ Soap Suds	☐ Excessive	☒ Water Line
☐ Fast	☐ Solvent	☐ Other:		☐ Other:
	☐ Chlorine			
	☐ Other:			

NOTE* If any of the above boxes are checked other than Dry or None, a photo must be taken and submitted as Attachment A.

D. ADDITIONAL NOTES

Central District, Happy Valley maintenance unit

ATTACHMENT A
Photo Documentation of Flows



Outfall ID: 1512550

Permit Year 2020



A. OUTFALL IDENTIFICATION

- 1) Outfall ID: 1512552
- 2) Date of Inspection: 2/7/2020
- 3) Time of Inspection: 12:08 pm
- 4) Rainfall event within the last 72 hour: ☐ yes ☒ no
- 5) Inspector Name: Laura Nordan and Alexis Zaring

B. GENERAL OUTFALL DESCRIPTION

- 1) Route: SR 101
- 2) Milepost: 16.73
- 3) Type of Outfall (ex. large cmp, step down box culvert):

Concrete-lined channel

C. FIELD OBSERVATIONS

Flow	Smell	Floatables	Vegetation/ Algae	Deposits
☐ Dry	☒ None	☒ None	☐ None	☒ None
☒ Standing	☐ Musty	☐ Sewage	☐ Minimal	☐ Debris
☐ Slow	☐ Sewage	☐ Oil Sheen	☒ Normal	☐ Sediment
☐ Moderate	☐ Rotten Eggs	☐ Soap Suds	☐ Excessive	☐ Water Line
☐ Fast	☐ Solvent	☐ Other:		☐ Other:
	☐ Chlorine			
	☐ Other:			

NOTE* If any of the above boxes are checked other than Dry or None, a photo must be taken and submitted as Attachment A.

D. ADDITIONAL NOTES

Central District, Happy Valley maintenance unit

No obvious source for standing water.

ATTACHMENT A
Photo Documentation of Flows



Outfall ID: 1512552

Permit Year 2020



A. OUTFALL IDENTIFICATION

- 1) Outfall ID: 1512556
- 2) Date of Inspection: 2/7/2020
- 3) Time of Inspection: 1:00 pm
- 4) Rainfall event within the last 72 hour: ☐ yes ☒ no
- 5) Inspector Name: Laura Nordan and Alexis Zaring

B. GENERAL OUTFALL DESCRIPTION

- 1) Route: SR 101
- 2) Milepost: 14.52
- 3) Type of Outfall (ex. large cmp, step down box culvert):

CBC 7x10x1

C. FIELD OBSERVATIONS

Flow

- ☒ Dry
☐ Standing
☐ Slow
☐ Moderate
☐ Fast

Smell

- ☒ None
☐ Musty
☐ Sewage
☐ Rotten Eggs
☐ Solvent
☐ Chlorine
☐ Other:

Floatables

- ☒ None
☐ Sewage
☐ Oil Sheen
☐ Soap Suds
☐ Other:

Vegetation/
Algae

- ☐ None
☐ Minimal
☐ Normal
☒ Excessive

Deposits

- ☐ None
☒ Debris
☒ Sediment
☐ Water Line
☐ Other:

NOTE* If any of the above boxes are checked other than Dry or None, a photo must be taken and submitted as Attachment A.

D. ADDITIONAL NOTES

Central District, Happy Valley maintenance unit

ATTACHMENT A
Photo Documentation of Flows



Outfall ID: 1512556

Permit Year 2020



A. OUTFALL IDENTIFICATION

- 1) Outfall ID: 1512558
- 2) Date of Inspection: 2/19/2020
- 3) Time of Inspection: 1:15 pm
- 4) Rainfall event within the last 72 hour: ☐ yes ☒ no
- 5) Inspector Name: Laura Nordan and Alexis Zaring

B. GENERAL OUTFALL DESCRIPTION

- 1) Route: US 60
- 2) Milepost: 159.57
- 3) Type of Outfall (ex. large cmp, step down box culvert):

Catch basin outlet, 36-inch

C. FIELD OBSERVATIONS

Flow	Smell	Floatables	Vegetation/ Algae	Deposits
☐ Dry	☒ None	☒ None	☒ None	☒ None
☒ Standing	☐ Musty	☐ Sewage	☐ Minimal	☐ Debris
☐ Slow	☐ Sewage	☐ Oil Sheen	☐ Normal	☐ Sediment
☐ Moderate	☐ Rotten Eggs	☐ Soap Suds	☐ Excessive	☐ Water Line
☐ Fast	☐ Solvent	☐ Other:		☐ Other:
	☐ Chlorine			
	☐ Other:			

NOTE* If any of the above boxes are checked other than Dry or None, a photo must be taken and submitted as Attachment A.

D. ADDITIONAL NOTES

Central District, Durango maintenance unit

Pipe opening partially submerged

ATTACHMENT A
Photo Documentation of Flows



Outfall ID:

1512558

Permit Year 2020



A. OUTFALL IDENTIFICATION

- 1) Outfall ID: 1516715
- 2) Date of Inspection: 3/18/2020
- 3) Time of Inspection: 9:45 am
- 4) Rainfall event within the last 72 hour: ☐ yes ☒ no
- 5) Inspector Name: Laura Nordan and Michael Carlson

B. GENERAL OUTFALL DESCRIPTION

- 1) Route: SR 77 NB
- 2) Milepost: 78.85
- 3) Type of Outfall (ex. large cmp, step down box culvert):

42-in pipe opening

C. FIELD OBSERVATIONS

Flow	Smell	Floatables	Vegetation/ Algae	Deposits
☒ Dry	☒ None	☒ None	☒ None	☒ None
☐ Standing	☐ Musty	☐ Sewage	☐ Minimal	☐ Debris
☐ Slow	☐ Sewage	☐ Oil Sheen	☐ Normal	☐ Sediment
☐ Moderate	☐ Rotten Eggs	☐ Soap Suds	☐ Excessive	☐ Water Line
☐ Fast	☐ Solvent	☐ Other:		☐ Other:
	☐ Chlorine			
	☐ Other:			

NOTE* If any of the above boxes are checked other than Dry or None, a photo must be taken and submitted as Attachment A.

D. ADDITIONAL NOTES

Southcentral District, Tucson East maintenance unit



A. OUTFALL IDENTIFICATION

- 1) Outfall ID: 1518523
- 2) Date of Inspection: 3/18/2020
- 3) Time of Inspection: 9:12 am
- 4) Rainfall event within the last 72 hour: ☐ yes ☒ no
- 5) Inspector Name: Laura Nordan and Michael Carlson

B. GENERAL OUTFALL DESCRIPTION

- 1) Route: SR 77 SB
- 2) Milepost: 80.86
- 3) Type of Outfall (ex. large cmp, step down box culvert):

24-in CMP

C. FIELD OBSERVATIONS

Flow	Smell	Floatables	Vegetation/ Algae	Deposits
☒ Dry	☒ None	☒ None	☒ None	☐ None
☐ Standing	☐ Musty	☐ Sewage	☐ Minimal	☐ Debris
☐ Slow	☐ Sewage	☐ Oil Sheen	☐ Normal	☐ Sediment
☐ Moderate	☐ Rotten Eggs	☐ Soap Suds	☐ Excessive	☒ Water Line
☐ Fast	☐ Solvent	☐ Other:		☐ Other:
	☐ Chlorine			
	☐ Other:			

NOTE* If any of the above boxes are checked other than Dry or None, a photo must be taken and submitted as Attachment A.

D. ADDITIONAL NOTES

Southcentral District, Tucson East maintenance unit

ATTACHMENT A
Photo Documentation of Flows



Outfall ID: 1518523

Permit Year 2020



A. OUTFALL IDENTIFICATION

- 1) Outfall ID: 1518814
- 2) Date of Inspection: 3/16/2020
- 3) Time of Inspection: 11:30 am
- 4) Rainfall event within the last 72 hour: ☐ yes ☒ no
- 5) Inspector Name: Laura Nordan

B. GENERAL OUTFALL DESCRIPTION

- 1) Route: SR 80
- 2) Milepost: 343.26
- 3) Type of Outfall (ex. large cmp, step down box culvert):

42-in CMP

C. FIELD OBSERVATIONS

Flow

- ☒ Dry
☐ Standing
☐ Slow
☐ Moderate
☐ Fast

Smell

- ☒ None
☐ Musty
☐ Sewage
☐ Rotten Eggs
☐ Solvent
☐ Chlorine
☐ Other:

Floatables

- ☒ None
☐ Sewage
☐ Oil Sheen
☐ Soap Suds
☐ Other:

Vegetation/
Algae

- ☒ None
☐ Minimal
☐ Normal
☐ Excessive

Deposits

- ☐ None
☐ Debris
☐ Sediment
☒ Water Line
☐ Other:

NOTE* If any of the above boxes are checked other than Dry or None, a photo must be taken and submitted as Attachment A.

D. ADDITIONAL NOTES

Southeast District, Douglas maintenance unit

ATTACHMENT A
Photo Documentation of Flows



Outfall ID: 1518814

Permit Year 2020



A. OUTFALL IDENTIFICATION

- 1) Outfall ID: 1518815
- 2) Date of Inspection: 3/16/2020
- 3) Time of Inspection: 11:33 am
- 4) Rainfall event within the last 72 hour: ☐ yes ☒ no
- 5) Inspector Name: Laura Nordan

B. GENERAL OUTFALL DESCRIPTION

- 1) Route: SR 80
- 2) Milepost: 343.26
- 3) Type of Outfall (ex. large cmp, step down box culvert):

18-in CMP

C. FIELD OBSERVATIONS

Flow

- ☒ Dry
☐ Standing
☐ Slow
☐ Moderate
☐ Fast

Smell

- ☒ None
☐ Musty
☐ Sewage
☐ Rotten Eggs
☐ Solvent
☐ Chlorine
☐ Other:

Floatables

- ☒ None
☐ Sewage
☐ Oil Sheen
☐ Soap Suds
☐ Other:

Vegetation/
Algae

- ☒ None
☐ Minimal
☐ Normal
☐ Excessive

Deposits

- ☐ None
☐ Debris
☐ Sediment
☒ Water Line
☐ Other:

NOTE* If any of the above boxes are checked other than Dry or None, a photo must be taken and submitted as Attachment A.

D. ADDITIONAL NOTES

Southeast District, Douglas maintenance unit

ATTACHMENT A
Photo Documentation of Flows



Outfall ID:

1518815

Permit Year 2020



A. OUTFALL IDENTIFICATION

- 1) Outfall ID: 1520653
- 2) Date of Inspection: 3/18/2020
- 3) Time of Inspection: 10:12 am
- 4) Rainfall event within the last 72 hour: ☐ yes ☒ no
- 5) Inspector Name: Laura Nordan and Michael Carlson

B. GENERAL OUTFALL DESCRIPTION

- 1) Route: SR 77 NB
- 2) Milepost: 71.81
- 3) Type of Outfall (ex. large cmp, step down box culvert):

66-in CMP

C. FIELD OBSERVATIONS

Flow

- ☐ Dry
☐ Standing
☐ Slow
☒ Moderate
☐ Fast

Smell

- ☒ None
☐ Musty
☐ Sewage
☐ Rotten Eggs
☐ Solvent
☐ Chlorine
☐ Other:

Floatables

- ☒ None
☐ Sewage
☐ Oil Sheen
☐ Soap Suds
☐ Other:

Vegetation/
Algae

- ☐ None
☐ Minimal
☒ Normal
☐ Excessive

Deposits

- ☐ None
☒ Debris
☐ Sediment
☒ Water Line
☐ Other:

Algae

NOTE* If any of the above boxes are checked other than Dry or None, a photo must be taken and submitted as Attachment A.

D. ADDITIONAL NOTES

Southcentral District, Tucson East maintenance unit

ATTACHMENT A
Photo Documentation of Flows



Outfall ID: 1520653

Permit Year 2020



A. OUTFALL IDENTIFICATION

- 1) Outfall ID: 1522248
- 2) Date of Inspection: 3/30/2020
- 3) Time of Inspection: 1222
- 4) Rainfall event within the last 72 hour: ☐ yes ☒ no
- 5) Inspector Name: Laura Nordan and Michael Carlson

B. GENERAL OUTFALL DESCRIPTION

- 1) Route: I-10 WB
- 2) Milepost: 284.65
- 3) Type of Outfall (ex. large cmp, step down box culvert):

48-in Concrete pipe

C. FIELD OBSERVATIONS

Flow	Smell	Floatables	Vegetation/ Algae	Deposits
☒ Dry	☒ None	☒ None	☒ None	☐ None
☐ Standing	☐ Musty	☐ Sewage	☐ Minimal	☐ Debris
☐ Slow	☐ Sewage	☐ Oil Sheen	☐ Normal	☒ Sediment
☐ Moderate	☐ Rotten Eggs	☐ Soap Suds	☐ Excessive	☐ Water Line
☐ Fast	☐ Solvent	☐ Other:		☐ Other:
	☐ Chlorine			
	☐ Other:			

NOTE* If any of the above boxes are checked other than Dry or None, a photo must be taken and submitted as Attachment A.

D. ADDITIONAL NOTES

Southcentral District, Tucson West maintenance unit

ATTACHMENT A
Photo Documentation of Flows



Outfall ID: 1522248

Permit Year 2020



A. OUTFALL IDENTIFICATION

- 1) Outfall ID: 1560894
- 2) Date of Inspection: 3/16/2020
- 3) Time of Inspection: 12:30 pm
- 4) Rainfall event within the last 72 hour: ☐ yes ☒ no
- 5) Inspector Name: Laura Nordan

B. GENERAL OUTFALL DESCRIPTION

- 1) Route: SR 80
- 2) Milepost: 297.71
- 3) Type of Outfall (ex. large cmp, step down box culvert):

4'x10'x12 CBC with deck drains

C. FIELD OBSERVATIONS

Flow	Smell	Floatables	Vegetation/ Algae	Deposits
☒ Dry	☒ None	☒ None	☒ None	☒ None
☐ Standing	☐ Musty	☐ Sewage	☐ Minimal	☐ Debris
☐ Slow	☐ Sewage	☐ Oil Sheen	☐ Normal	☐ Sediment
☐ Moderate	☐ Rotten Eggs	☐ Soap Suds	☐ Excessive	☐ Water Line
☐ Fast	☐ Solvent	☐ Other:		☐ Other:
	☐ Chlorine			
	☐ Other:			

NOTE* If any of the above boxes are checked other than Dry or None, a photo must be taken and submitted as Attachment A.

D. ADDITIONAL NOTES

Southcentral District, St. David maintenance unit

The asset number is a duplicate of 1518809 (inactive).



A. OUTFALL IDENTIFICATION

- 1) Outfall ID: 2000246
- 2) Date of Inspection: 3/5/2020
- 3) Time of Inspection: 10:45 am
- 4) Rainfall event within the last 72 hour: ☐ yes ☒ no
- 5) Inspector Name: Laura Nordan and Alexis Zaring

B. GENERAL OUTFALL DESCRIPTION

- 1) Route: SR 202 EB
- 2) Milepost: 7.45
- 3) Type of Outfall (ex. large cmp, step down box culvert):

48-in CMP

C. FIELD OBSERVATIONS

Flow

- ☐ Dry
☒ Standing
☐ Slow
☐ Moderate
☐ Fast

Smell

- ☒ None
☐ Musty
☐ Sewage
☐ Rotten Eggs
☐ Solvent
☐ Chlorine
☐ Other:

Floatables

- ☒ None
☐ Sewage
☐ Oil Sheen
☐ Soap Suds
☐ Other:

Vegetation/
Algae

- ☒ None
☐ Minimal
☐ Normal
☐ Excessive

Deposits

- ☒ None
☐ Debris
☐ Sediment
☐ Water Line
☐ Other:

NOTE* If any of the above boxes are checked other than Dry or None, a photo must be taken and submitted as Attachment A.

D. ADDITIONAL NOTES

Central District, University maintenance unit

Outfall submerged by Tempe Town Lake

ATTACHMENT A
Photo Documentation of Flows



Outfall ID: 2000246

Permit Year 2020



A. OUTFALL IDENTIFICATION

- 1) Outfall ID: 2029182
- 2) Date of Inspection: 3/30/2020
- 3) Time of Inspection: 1054
- 4) Rainfall event within the last 72 hour: ☐ yes ☒ no
- 5) Inspector Name: Laura Nordan and Michael Carlson

B. GENERAL OUTFALL DESCRIPTION

- 1) Route: I-10 EB
- 2) Milepost: 289.14
- 3) Type of Outfall (ex. large cmp, step down box culvert):

18-in CMP with flared metal end

C. FIELD OBSERVATIONS

Flow

- ☒ Dry
☐ Standing
☐ Slow
☐ Moderate
☐ Fast

Smell

- ☒ None
☐ Musty
☐ Sewage
☐ Rotten Eggs
☐ Solvent
☐ Chlorine
☐ Other:

Floatables

- ☒ None
☐ Sewage
☐ Oil Sheen
☐ Soap Suds
☐ Other:

Vegetation/
Algae

- ☒ None
☐ Minimal
☐ Normal
☐ Excessive

Deposits

- ☐ None
☒ Debris
☒ Sediment
☒ Water Line
☐ Other:

NOTE* If any of the above boxes are checked other than Dry or None, a photo must be taken and submitted as Attachment A.

D. ADDITIONAL NOTES

Southcentral District, Tucson West maintenance unit

ATTACHMENT A
Photo Documentation of Flows



Outfall ID: 2029182

Permit Year 2020



A. OUTFALL IDENTIFICATION

- 1) Outfall ID: 2029183
- 2) Date of Inspection: 3/30/2020
- 3) Time of Inspection: 1055
- 4) Rainfall event within the last 72 hour: ☐ yes ☒ no
- 5) Inspector Name: Laura Nordan and Michael Carlson

B. GENERAL OUTFALL DESCRIPTION

- 1) Route: I-10 WB
- 2) Milepost: 289.14
- 3) Type of Outfall (ex. large cmp, step down box culvert):

18-in CMP with flared metal end

C. FIELD OBSERVATIONS

Flow	Smell	Floatables	Vegetation/ Algae	Deposits
☒ Dry	☒ None	☒ None	☐ None	☐ None
☐ Standing	☐ Musty	☐ Sewage	☐ Minimal	☐ Debris
☐ Slow	☐ Sewage	☐ Oil Sheen	☒ Normal	☒ Sediment
☐ Moderate	☐ Rotten Eggs	☐ Soap Suds	☐ Excessive	☐ Water Line
☐ Fast	☐ Solvent	☐ Other:		☐ Other:
	☐ Chlorine			
	☐ Other:			

NOTE* If any of the above boxes are checked other than Dry or None, a photo must be taken and submitted as Attachment A.

D. ADDITIONAL NOTES

Southcentral District, Tucson West maintenance unit

ATTACHMENT A
Photo Documentation of Flows



Outfall ID: 2029183

Permit Year 2020



A. OUTFALL IDENTIFICATION

- 1) Outfall ID: 2029184
- 2) Date of Inspection: 3/30/2020
- 3) Time of Inspection: 1100
- 4) Rainfall event within the last 72 hour: ☐ yes ☒ no
- 5) Inspector Name: Laura Nordan and Michael Carlson

B. GENERAL OUTFALL DESCRIPTION

- 1) Route: I-10 EB
- 2) Milepost: 289.11
- 3) Type of Outfall (ex. large cmp, step down box culvert):

18-in CMP with flared metal end

C. FIELD OBSERVATIONS

Flow

- ☒ Dry
☐ Standing
☐ Slow
☐ Moderate
☐ Fast

Smell

- ☒ None
☐ Musty
☐ Sewage
☐ Rotten Eggs
☐ Solvent
☐ Chlorine
☐ Other:

Floatables

- ☒ None
☐ Sewage
☐ Oil Sheen
☐ Soap Suds
☐ Other:

Vegetation/
Algae

- ☒ None
☐ Minimal
☐ Normal
☐ Excessive

Deposits

- ☐ None
☒ Debris
☒ Sediment
☒ Water Line
☐ Other:

NOTE* If any of the above boxes are checked other than Dry or None, a photo must be taken and submitted as Attachment A.

D. ADDITIONAL NOTES

Southcentral District, Tucson West maintenance unit

ATTACHMENT A
Photo Documentation of Flows



Outfall ID: 2029184

Permit Year 2020



A. OUTFALL IDENTIFICATION

- 1) Outfall ID: 2029186
- 2) Date of Inspection: 3/30/2020
- 3) Time of Inspection: 1103
- 4) Rainfall event within the last 72 hour: ☐ yes ☒ no
- 5) Inspector Name: Laura Nordan and Michael Carlson

B. GENERAL OUTFALL DESCRIPTION

- 1) Route: I-10 EB
- 2) Milepost: 289.10
- 3) Type of Outfall (ex. large cmp, step down box culvert):

18-in CMP with flared metal end

C. FIELD OBSERVATIONS

Flow	Smell	Floatables	Vegetation/ Algae	Deposits
☒ Dry	☒ None	☒ None	☒ None	☒ None
☐ Standing	☐ Musty	☐ Sewage	☐ Minimal	☐ Debris
☐ Slow	☐ Sewage	☐ Oil Sheen	☐ Normal	☐ Sediment
☐ Moderate	☐ Rotten Eggs	☐ Soap Suds	☐ Excessive	☐ Water Line
☐ Fast	☐ Solvent	☐ Other:		☐ Other:
	☐ Chlorine			
	☐ Other:			

NOTE* If any of the above boxes are checked other than Dry or None, a photo must be taken and submitted as Attachment A.

D. ADDITIONAL NOTES

Southcentral District, Tucson West maintenance unit



A. OUTFALL IDENTIFICATION

- 1) Outfall ID: 2029187
- 2) Date of Inspection: 3/30/2020
- 3) Time of Inspection: 1105
- 4) Rainfall event within the last 72 hour: ☐ yes ☒ no
- 5) Inspector Name: Laura Nordan and Michael Carlson

B. GENERAL OUTFALL DESCRIPTION

- 1) Route: I-10 WB
- 2) Milepost: 289.10
- 3) Type of Outfall (ex. large cmp, step down box culvert):

18-in CMP with flared metal end

C. FIELD OBSERVATIONS

Flow

- ☒ Dry
☐ Standing
☐ Slow
☐ Moderate
☐ Fast

Smell

- ☒ None
☐ Musty
☐ Sewage
☐ Rotten Eggs
☐ Solvent
☐ Chlorine
☐ Other:

Floatables

- ☒ None
☐ Sewage
☐ Oil Sheen
☐ Soap Suds
☐ Other:

Vegetation/
Algae

- ☒ None
☐ Minimal
☐ Normal
☐ Excessive

Deposits

- ☒ None
☐ Debris
☐ Sediment
☐ Water Line
☐ Other:

NOTE* If any of the above boxes are checked other than Dry or None, a photo must be taken and submitted as Attachment A.

D. ADDITIONAL NOTES

Southcentral District, Tucson West maintenance unit



A. OUTFALL IDENTIFICATION

- 1) Outfall ID: 2029195
- 2) Date of Inspection: 3/30/2020
- 3) Time of Inspection: 1207
- 4) Rainfall event within the last 72 hour: ☐ yes ☒ no
- 5) Inspector Name: Laura Nordan and Michael Carlson

B. GENERAL OUTFALL DESCRIPTION

- 1) Route: I-10 WB
- 2) Milepost: 289.24
- 3) Type of Outfall (ex. large cmp, step down box culvert):

Concrete spillway

C. FIELD OBSERVATIONS

Flow

- ☒ Dry
☐ Standing
☐ Slow
☐ Moderate
☐ Fast

Smell

- ☒ None
☐ Musty
☐ Sewage
☐ Rotten Eggs
☐ Solvent
☐ Chlorine
☐ Other:

Floatables

- ☒ None
☐ Sewage
☐ Oil Sheen
☐ Soap Suds
☐ Other:

Vegetation/
Algae

- ☐ None
☒ Minimal
☐ Normal
☐ Excessive

Deposits

- ☐ None
☒ Debris
☒ Sediment
☒ Water Line
☐ Other:

NOTE* If any of the above boxes are checked other than Dry or None, a photo must be taken and submitted as Attachment A.

D. ADDITIONAL NOTES

Southcentral District, Tucson West maintenance unit

ATTACHMENT A
Photo Documentation of Flows



Outfall ID:

2029195

Permit Year 2020



A. OUTFALL IDENTIFICATION

- 1) Outfall ID:
- 2) Date of Inspection:
- 3) Time of Inspection:
- 4) Rainfall event within the last 72 hour: ☐ yes ☒ no
- 5) Inspector Name:

B. GENERAL OUTFALL DESCRIPTION

- 1) Route:
- 2) Milepost:
- 3) Type of Outfall (ex. large cmp, step down box culvert):

C. FIELD OBSERVATIONS

Flow	Smell	Floatables	Vegetation/ Algae	Deposits
☒ Dry	☒ None	☒ None	☒ None	☐ None
☐ Standing	☐ Musty	☐ Sewage	☐ Minimal	☒ Debris
☐ Slow	☐ Sewage	☐ Oil Sheen	☐ Normal	☒ Sediment
☐ Moderate	☐ Rotten Eggs	☐ Soap Suds	☐ Excessive	☒ Water Line
☐ Fast	☐ Solvent	☐ Other:		☐ Other:
	☐ Chlorine			
	☐ Other:			

NOTE* If any of the above boxes are checked other than Dry or None, a photo must be taken and submitted as Attachment A.

D. ADDITIONAL NOTES

ATTACHMENT A
Photo Documentation of Flows



Outfall ID:

2029486

Permit Year 2020