




US 89 Closed South of Page due to Landslide US 89 Detour and Repair Details

On Feb 20, 2013, a landslide ripped through a section of US 89 along a mountain slope about 25 miles south of Page, buckling more than 150 feet of the roadway and tearing the pavement up in six-foot high sections.

The significant roadway damage forced the Arizona Department of Transportation to immediately close a 23-mile-long stretch of the highway (at mileposts 523-546) between the US 89A junction near Bitter Springs to the State Route 98 junction near Page.


US 89 DETOUR MAP AND INFORMATION

- ▶ US 89T is open between Page and Gap. This detour begins at milepost 498 on US 89 and intersects with SR 98 in Page.
- ▶ Access to the Grand Canyon North Rim Entrance, Jacob Lake, Lee's Ferry, Marble Canyon, Vermilion Cliffs is open using US 89A.



ROADWAY REPAIR UNDERWAY

At this time ADOT is currently working on the repairs to the roadway. The repair work includes moving the road alignment approximately 60 feet away from the landslide area and stabilizing the new road by constructing a downslope buttress. The material for the buttress will be provided by excavating the landslide area by blasting, removing and hauling the rock below the new roadway to further reinforce the repairs. ADOT anticipates completion of the US 89 repair and opening the new segment for travel by early summer, 2015.



14-369



For more information, visit the project website: azdot.gov/us89
For questions, call 855.712.8530 or email projects@azdot.gov