

Steep cliffs and slopes





Engineering Issues





Drainage and erosion



Bridge rehabilitation/ repairs are needed

State Route 88 (Apache Trail), Milepost 222 to 229





Guardrail is damaged and in poor condition

Narrow roadway, eroded surface

