


Phoenix area freeway restrictions:

Please Note: Times listed are subject to change. Slow down and merge safely in work zones.

- 1 SR 51 SB closed between Glendale Ave and Indian School Rd for pavement improvement project. SR 51 SB on-ramp at Northern Ave also closed. Detours:** Consider using I-17 SB as an alternate freeway route to downtown Phoenix and Sky Harbor Airport. Drivers exiting SR 51 SB at Northern or Glendale avenues can detour south on 16th St before entering the freeway via Indian School or Thomas roads.
9 p.m. Fri – 5 a.m. Mon (March 30)
- 2 Loop 101 WB (Agua Fria Freeway) closed between I-17 and 51st Ave for widening project. I-17 NB and SB ramps to Loop 101 WB closed. Loop 101 WB on-ramps at Seventh St and Seventh Ave closed. Detour:** Consider alternate routes while Loop 101 WB is closed, including WB Bell Rd and Union Hills Dr.
10 p.m. Fri – 5 a.m. Mon (March 30)
Note: I-17 NB narrowed to two lanes between Loop 101 and Pinnacle Peak Rd. **9 p.m. Fri – 5 p.m. Sun (March 29)**
- 3 I-10 WB on-ramp connection from SB Seventh Street (south of McDowell Rd) closed for paving work. Detour:** Consider entering I-10 WB via 16th St or Seventh Ave.
10 p.m. Fri – 5 a.m. Mon (March 30)
- 4 Lindsay Rd closed in both directions at Loop 202 (Santan Freeway) for widening project. Detours:** Consider using Pecos or Germann roads to Gilbert Rd or Val Vista Dr to travel beyond Loop 202.
10 p.m. Fri – 2 p.m. Sat (March 28)



Additional freeway restriction information can be listed on azdot.gov

